

<i>MICS RLS IT1 CTX</i>	Yes	No	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
<i>MICS CDA XC 1.0</i>	No	No	No	No	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes
<i>MICS USA XL</i>	No	No	No	No	Yes	Yes	Yes	Yes	Yes	No	Yes	Yes	Yes	Yes	Yes
<i>MICS USA XC 1.0</i>	No	No	No	No	Yes	Yes	Yes	Yes	Yes	No	No	Yes	Yes	Yes	Yes
<i>MICS RLS1 T1 DR1.1</i>	Yes	No	No	No	Yes	Yes	Yes	Yes	Yes	No	No	Yes	Yes	Yes	Yes
<i>MICS CDA/USA XC 1.1</i>	No	No	No	No	Yes	Yes	Yes	Yes	Yes	No	No	Yes	Yes	Yes	Yes
<i>MICS 2.0</i>	No	No	No	No	No	No	Yes	Yes	Yes	No	No	No	Yes	Yes	Yes
<i>MICS XC 2.0</i>	No	No	No	No	No	No	Yes	Yes	Yes	No	No	No	Yes	Yes	Yes
<i>MICS 3.0</i>	No	No	No	No	No	No	Yes	Yes	Yes	No	No	No	Yes	Yes	Yes
<i>MICS XC 3.0</i>	No	No	No	No	No	No	Yes	Yes	Yes	No	No	No	Yes	Yes	Yes
<i>CICS 1.0</i>	No	No	No	No	Yes	Yes	Yes	Yes	Yes	No	No	Yes	Yes	Yes	Yes
<i>CICS 2.0</i>	No	No	No	No	No	No	Yes	Yes	Yes	No	No	No	Yes	Yes	Yes
<i>MICS 4.0</i>	No	No	No	No	No	No	No	No	Yes	No	No	No	No	No	Yes
<i>MICS XC 4.0</i>	No	No	No	No	No	No	No	No	Yes	No	No	No	No	No	Yes
<i>CICS 4.0</i>	No	No	No	No	No	No	No	No	Yes	No	No	No	No	No	Yes

Note 1: For customers with StarTalk Versions 1.5, 1.6, 2.0, 2.01, 2.01a, 2.02, 2.03, and 2.04I, there is a free upgrade package to Version 2.04L.

Note 2: Minimum version of DR5 on 3x8 is SP: SP: 30NPE07

Note 3: Minimum version of DR5 on 6x16 DS is SP: 30NSE08 eng/fre or 30NTE08 eng/spa
Minimum version of DR5 on 6x16 non DS is SP: 30MJJ21 eng/fre or 30MKJ21 eng/spa

Note 4: Minimum version of DR5 on 8x24 is SP: 30MUL07 eng/fre or 30MVL07 eng/spa

Note 5: Minimum version of DR5 Centrex on 8x24 is SP: 30MGJ22 eng/fre or 30MHJ22 eng/spa

Note 6: This is for voice mail only. The FlashACD product is not compatible with anything but CICS/MICs.